


DEC 03 19.

MACHINE SHOP
ANDY/DAVE

COCKLES SHOP CONT.
RENTS

- STARTING CUTTING AND DRILLING EXCESSIVE.



METHOD.

- FILE OFF BURRS FROM NEW WORK BLOCK
- FIND SQUAREST CORNER AND MARK FOR REFERENCE
- USING SQUARE TABLE AND EDGE, MEASURE DIMENSIONS AND SCRIBE WITH DIGITAL HEIGHT GAGE