


LIVE OPVIES, 05/02/2021, TIME: 2 PM

1707263

ADVANCED STRESS + FEA M6X00426



Most test results fall between the Goodman and Gerber curves. However, with Soderberg giving a margin of safety this is often used.

For example, the stress experienced on an aircraft wing the use of Soderberg with the additional factor of safety, although the likelihood is the wing could be subjected to greater stress. The use of Soderberg would cause failure of the material is not experienced.