




Technium Business Park

Warning: PDF designed for A4 colour print only with no page scaling



Contact Us

Mapping Enquiries:

All areas 02920 278 912

General Enquiries:

All areas 0800 912 2999

Dig Sites

Area:

Line:



Low Pressure (LP) 21mbar – 75mbar



Medium Pressure (MP) 350mbar – 2bar



Intermediate Pressure (IP) 2bar – 7bar



High Pressure (HP) >7bar



Change of Diameter



End Cap



Depth of cover



Line/Fire Valve



Governor Station

EXTREME CAUTION.
Major Accident Hazard Pipeline in Vicinity
****RISK OF DEATH OR SERIOUS INJURY****
Prior to excavation starting you must contact the plant protection team on 02920 278912

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Date Requested: 15/02/2019
Job Reference: 14851396
Site Location: 265772 191819
Requested by: Mr Sam Pogson
Your Scheme/Reference: asdf

Scale: 1:1250 (When plotted at A4)


Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2019. All rights reserved. Ordnance Survey Licence number 0100044308.

Smell gas?
Call the Gas Emergency Service on
0800 111 999.

Dial
before
you dig

We need
10 days'
notice

Dial
Call **029 2027 8912**
before you start work.
Investigate
Before you dig, make sure
you know what's below.
Go ahead
Done your research?
Now you can dig safely.



Contact Us

Mapping Enquiries:

All areas 02920 278 912

General Enquiries:

All areas 0800 912 2999

Date Requested: 15/02/2019

Job Reference: 14851396

Site Location: 265772 191819

Requested by: Mr Sam Pogson

Your Scheme/Reference: asdf

Scale: 1:1250 (When plotted at A4)

100m

Dig Sites

Area:

Line:

Low Pressure (LP) 21mbar – 75mbar

Medium Pressure (MP) 350mbar – 2bar

Intermediate Pressure (IP) 2bar – 7bar

High Pressure (HP) >7bar



Change of Diameter



End Cap



Depth of cover



Line/Fire Valve



Governor Station

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WUU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with H5(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WUU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2019. All rights reserved. Ordnance Survey Licence number 0100044308.

EXTREME CAUTION.
Major Accident Hazard Pipeline in Vicinity
RISK OF DEATH OR SERIOUS INJURY
Prior to excavation starting you must contact the plant protection team on 02920 278912

Smell gas?
Call the Gas Emergency Service on
0800 111 999.


Dial
before
you dig

We need
10 days'
notice

Dial
Call 029 2027 8912
before you start work.

Investigate
Before you dig, make sure
you know what's below.

Go ahead
Done your research?
Now you can dig safely.



Warning: PDF designed for A4 colour print only with no page scaling



Contact Us

Mapping Enquiries:

All areas 02920 278 912

General Enquiries:

All areas 0800 912 2999

Dig Sites

Area:

Line:



Low Pressure (LP) 21mbar – 75mbar



Medium Pressure (MP) 350mbar – 2bar



Intermediate Pressure (IP) 2bar – 7bar



High Pressure (HP) >7bar



Change of Diameter



End Cap



Depth of cover



Line/Fire Valve



Governor Station

EXTREME CAUTION.
Major Accident Hazard Pipeline in Vicinity
****RISK OF DEATH OR SERIOUS INJURY****
Prior to excavation starting you must contact the plant protection team on 02920 278912

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HSG47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Date Requested: 15/02/2019
Job Reference: 14851396
Site Location: 265772 191819
Requested by: Mr Sam Pogson
Your Scheme/Reference: asdf

Scale: 1:1250 (When plotted at A4)

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2019. All rights reserved. Ordnance Survey Licence number 0100044308.

Smell gas?
Call the Gas Emergency Service on
0800 111 999.


Dial
before
you dig

We need
10 days'
notice

Dial
Call **029 2027 8912**
before you start work.

Investigate
Before you dig, make sure
you know what's below.

Go ahead
Done your research?
Now you can dig safely.



Warning: PDF designed for A4 colour print only with no page scaling



Contact Us

Mapping Enquiries:

All areas 02920 278 912

General Enquiries:

All areas 0800 912 2999

100m

Dig Sites

Area:

Line:

Low Pressure (LP) 21mbar – 75mbar

Medium Pressure (MP) 350mbar – 2bar

Intermediate Pressure (IP) 2bar – 7bar

High Pressure (HP) >7bar



Change of Diameter



End Cap



Depth of cover



Line/Fire Valve



Governor Station

EXTREME CAUTION.
Major Accident Hazard Pipeline in Vicinity
****RISK OF DEATH OR SERIOUS INJURY****
Prior to excavation starting you must contact the plant protection team on 02920 278912

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Date Requested: 15/02/2019
Job Reference: 14851396
Site Location: 265772 191819
Requested by: Mr Sam Pogson
Your Scheme/Reference: asdf

Scale: 1:1250 (When plotted at A4)

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2019. All rights reserved. Ordnance Survey Licence number 0100044308.

Smell gas?
Call the Gas Emergency Service on
0800 111 999.


Dial
before
you dig

We need
10 days'
notice

Dial
Call **029 2027 8912**
before you start work.

Investigate
Before you dig, make sure
you know what's below.

Go ahead
Done your research?
Now you can dig safely.



Contact Us

Mapping Enquiries:

All areas 02920 278 912

General Enquiries:

All areas 0800 912 2999

Dig Sites

Area:

Line:

	Low Pressure (LP) 21mbar – 75mbar
	Medium Pressure (MP) 350mbar – 2bar
	Intermediate Pressure (IP) 2bar – 7bar
	High Pressure (HP) >7bar



Change of Diameter



End Cap



Depth of cover



Line/Fire Valve



Governor Station

EXTREME CAUTION.
Major Accident Hazard Pipeline in Vicinity
****RISK OF DEATH OR SERIOUS INJURY****
Prior to excavation starting you must contact the plant protection team on 02920 278912

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with H5(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Date Requested: 15/02/2019
Job Reference: 14851396
Site Location: 265772 191819
Requested by: Mr Sam Pogson
Your Scheme/Reference: asdf

Scale: 1:1250 (When plotted at A4)

Smell gas?
Call the Gas Emergency Service on
0800 111 999.


Dial
before
you dig

We need
10 days'
notice

Dial
Call **029 2027 8912**
before you start work.

Investigate
Before you dig, make sure
you know what's below.

Go ahead
Done your research?
Now you can dig safely.



Warning: PDF designed for A4 colour print only with no page scaling



Contact Us

Mapping Enquiries:

All areas 02920 278 912

General Enquiries:

All areas 0800 912 2999

Dig Sites

Area:

Line:



Low Pressure (LP) 21mbar – 75mbar



Medium Pressure (MP) 350mbar – 2bar



Intermediate Pressure (IP) 2bar – 7bar



High Pressure (HP) >7bar



Change of Diameter



End Cap



Depth of cover



Line/Fire Valve



Governor Station

EXTREME CAUTION.
Major Accident Hazard Pipeline in Vicinity
****RISK OF DEATH OR SERIOUS INJURY****
Prior to excavation starting you must contact the plant protection team on 02920 278912

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with H5(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Date Requested: 15/02/2019
Job Reference: 14851396
Site Location: 265772 191819
Requested by: Mr Sam Pogson
Your Scheme/Reference: asdf

Scale: 1:1250 (When plotted at A4)

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2019. All rights reserved. Ordnance Survey Licence number 0100044308.

Smell gas?
Call the Gas Emergency Service on
0800 111 999.


Dial
before
you dig

We need
10 days
notice

Dial
Call **029 2027 8912**
before you start work.

Investigate
Before you dig, make sure
you know what's below.

Go ahead
Done your research?
Now you can dig safely.



Warning: PDF designed for A4 colour print only with no page scaling



Contact Us

Mapping Enquiries:

All areas 02920 278 912

General Enquiries:

All areas 0800 912 2999

Dig Sites

Area:

Line:



Low Pressure (LP) 21mbar – 75mbar



Medium Pressure (MP) 350mbar – 2bar



Intermediate Pressure (IP) 2bar – 7bar



High Pressure (HP) >7bar



Change of Diameter



End Cap



Depth of cover



Line/Fire Valve



Governor Station

EXTREME CAUTION.
Major Accident Hazard Pipeline in Vicinity
****RISK OF DEATH OR SERIOUS INJURY****
Prior to excavation starting you must contact the plant protection team on 02920 278912

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Date Requested: 15/02/2019
Job Reference: 14851396
Site Location: 265772 191819
Requested by: Mr Sam Pogson
Your Scheme/Reference: asdf

Scale: 1:1250 (When plotted at A4)

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2019. All rights reserved. Ordnance Survey Licence number 0100044308.

Smell gas?
Call the Gas Emergency Service on
0800 111 999.


Dial
before
you dig

We need
10 days'
notice

Dial
Call **029 2027 8912**
before you start work.

Investigate
Before you dig, make sure
you know what's below.

Go ahead
Done your research?
Now you can dig safely.



Contact Us

Mapping Enquiries:

All areas 02920 278 912

General Enquiries:

All areas 0800 912 2999

Dig Sites

Area:

Line:

Low Pressure (LP) 21mbar – 75mbar

Medium Pressure (MP) 350mbar – 2bar

Intermediate Pressure (IP) 2bar – 7bar

High Pressure (HP) >7bar

Change of Diameter

End Cap

Depth of cover

Depth of cover

Change of Diameter

End Cap

Depth of cover

Line/Fire Valve

Governor Station

EXTREME CAUTION.

Major Accident Hazard Pipeline in Vicinity
RISK OF DEATH OR SERIOUS INJURY
Prior to excavation starting you must contact the plant protection team on 02920 278912

Date Requested: 15/02/2019
Job Reference: 14851396
Site Location: 265772 191819
Requested by: Mr Sam Pogson
Your Scheme/Reference: asdf

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WUU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WUU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Scale: 1:1250 (When plotted at A4)

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2019. All rights reserved. Ordnance Survey Licence number 0100044308.

Smell gas?
Call the Gas Emergency Service on
0800 111 999.


Dial
before
you dig

We need
10 days'
notice

Dial
Call 029 2027 8912
before you start work.

Investigate
Before you dig, make sure
you know what's below.

Go ahead
Done your research?
Now you can dig safely.



Wales & West Utilities

Contact Us
Mapping Enquiries:
All areas 02920 278 912
General Enquiries:
All areas 0800 912 2999

100m

Dig Sites	Area:	Line:			
	Low Pressure (LP) 21mbar – 75mbar		Change of Diameter		Line/Fire Valve
	Medium Pressure (MP) 350mbar – 2bar		End Cap		Governor Station
	Intermediate Pressure (IP) 2bar – 7bar		Depth of cover		
	High Pressure (HP) >7bar				

EXTREME CAUTION.
Major Accident Hazard Pipeline in Vicinity
****RISK OF DEATH OR SERIOUS INJURY****
Prior to excavation starting you must contact the plant protection team on 02920 278912

Date Requested: 15/02/2019
Job Reference: 14851396
Site Location: 265772 191819
Requested by: Mr Sam Pogson
Your Scheme/Reference: asdf

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Smell gas?
Call the Gas Emergency Service on
0800 111 999.

Dial before you dig


We need 10 days' notice

Dial
Call **029 2027 8912**
before you start work.

Investigate
Before you dig, make sure you know what's below.

Go ahead
Done your research? Now you can dig safely.

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2019. All rights reserved. Ordnance Survey Licence number 0100044308.



Contact Us

Mapping Enquiries:

All areas 02920 278 912

General Enquiries:

All areas 0800 912 2999



Dig Sites

Area:

Line:



Low Pressure (LP) 21mbar – 75mbar



Medium Pressure (MP) 350mbar – 2bar



Intermediate Pressure (IP) 2bar – 7bar



High Pressure (HP) >7bar



Change of Diameter



End Cap



Depth of cover



Line/Fire Valve



Governor Station

EXTREME CAUTION.
Major Accident Hazard Pipeline in Vicinity
****RISK OF DEATH OR SERIOUS INJURY****
Prior to excavation starting you must contact the plant protection team on 02920 278912

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Date Requested: 15/02/2019
Job Reference: 14851396
Site Location: 265772 191819
Requested by: Mr Sam Pogson
Your Scheme/Reference: asdf

Scale: 1:1250 (When plotted at A4)

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2019. All rights reserved. Ordnance Survey Licence number 0100044308.

Dial
before
you dig


We need
10 days'
notice

Smell gas?
Call the Gas Emergency Service on
0800 111 999.

Dial
Call **029 2027 8912**
before you start work.

Investigate
Before you dig, make sure
you know what's below.

Go ahead
Done your research?
Now you can dig safely.



Contact Us

Mapping Enquiries:

All areas 02920 278 912

General Enquiries:

All areas 0800 912 2999

100m

Dig Sites

Area:

Line:



Low Pressure (LP) 21mbar – 75mbar



Medium Pressure (MP) 350mbar – 2bar



Intermediate Pressure (IP) 2bar – 7bar



High Pressure (HP) >7bar



Change of Diameter



End Cap



Depth of cover



Line/Fire Valve



Governor Station

EXTREME CAUTION.
Major Accident Hazard Pipeline in Vicinity
****RISK OF DEATH OR SERIOUS INJURY****
Prior to excavation starting you must contact the plant protection team on 02920 278912

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Date Requested: 15/02/2019
Job Reference: 14851396
Site Location: 265772 191819
Requested by: Mr Sam Pogson
Your Scheme/Reference: asdf

Scale: 1:1250 (When plotted at A4)

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2019. All rights reserved. Ordnance Survey Licence number 0100044308.

Smell gas?
Call the Gas Emergency Service on
0800 111 999.


Dial
before
you dig

We need
10 days'
notice

Dial
Call **029 2027 8912**
before you start work.


Investigate
Before you dig, make sure
you know what's below.

Go ahead
Done your research?
Now you can dig safely.




			EXTREME CAUTION. Major Accident Hazard Pipeline in Vicinity **RISK OF DEATH OR SERIOUS INJURY** Prior to excavation starting you must contact the plant protection team on 02920 278912																										
Contact Us Mapping Enquiries: All areas 02920 278 912 General Enquiries: All areas 0800 912 2999	<table border="0"> <tr> <td>Dig Sites</td> <td>Area: </td> <td>Line: </td> </tr> <tr> <td></td> <td colspan="2">Low Pressure (LP) 21mbar – 75mbar</td> </tr> <tr> <td></td> <td colspan="2">Medium Pressure (MP) 350mbar – 2bar</td> </tr> <tr> <td></td> <td colspan="2">Intermediate Pressure (IP) 2bar – 7bar</td> </tr> <tr> <td></td> <td colspan="2">High Pressure (HP) >7bar</td> </tr> </table>	Dig Sites		Area:	Line:		Low Pressure (LP) 21mbar – 75mbar			Medium Pressure (MP) 350mbar – 2bar			Intermediate Pressure (IP) 2bar – 7bar			High Pressure (HP) >7bar		<table border="0"> <tr> <td></td> <td>Change of Diameter</td> <td></td> <td>Line/Fire Valve</td> </tr> <tr> <td></td> <td>End Cap</td> <td></td> <td>Governor Station</td> </tr> <tr> <td></td> <td>Depth of cover</td> <td></td> <td></td> </tr> </table>		Change of Diameter		Line/Fire Valve		End Cap		Governor Station		Depth of cover	
Dig Sites	Area:	Line:																											
	Low Pressure (LP) 21mbar – 75mbar																												
	Medium Pressure (MP) 350mbar – 2bar																												
	Intermediate Pressure (IP) 2bar – 7bar																												
	High Pressure (HP) >7bar																												
	Change of Diameter		Line/Fire Valve																										
	End Cap		Governor Station																										
	Depth of cover																												
Date Requested: 15/02/2019 Job Reference: 14851396 Site Location: 265772 191819 Requested by: Mr Sam Pogson Your Scheme/Reference: asdf	IMPORTANT NOTICES - This information is given as a guide only and its accuracy cannot be guaranteed - The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter - Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated - You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used - It is your responsibility to ensure this information is provided to all persons working near our plant - If in doubt call the WWU dig team on 02920 27891 Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA 0800 111 999																												

Scale: 1:1250 (When plotted at A4)



 WALES&WEST UTILITIES		
--	---	--



Warning: PDF designed for A4 colour print only with no page scaling



Contact Us

Mapping Enquiries:

All areas 02920 278 912

General Enquiries:

All areas 0800 912 2999

Dig Sites

Area:

Line:

Low Pressure (LP) 21mbar – 75mbar

Medium Pressure (MP) 350mbar – 2bar

Intermediate Pressure (IP) 2bar – 7bar

High Pressure (HP) >7bar

Low Pressure (LP) 21mbar – 75mbar

Medium Pressure (MP) 350mbar – 2bar

Intermediate Pressure (IP) 2bar – 7bar

High Pressure (HP) >7bar



Change of Diameter



End Cap



Depth of cover



Line/Fire Valve



Governor Station

EXTREME CAUTION.

Major Accident Hazard Pipeline in Vicinity
RISK OF DEATH OR SERIOUS INJURY
Prior to excavation starting you must contact the plant protection team on 02920 278912

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Date Requested: 15/02/2019
Job Reference: 14851396
Site Location: 265772 191819
Requested by: Mr Sam Pogson
Your Scheme/Reference: asdf


Scale: 1:1250 (When plotted at A4)

Smell gas?
Call the Gas Emergency Service on
0800 111 999.

Dial
before
you dig

We need
10 days'
notice

Dial
Call **029 2027 8912**
before you start work.
Investigate
Before you dig, make sure
you know what's below.
Go ahead
Done your research?
Now you can dig safely.



Contact Us

Mapping Enquiries:

All areas 02920 278 912

General Enquiries:

All areas 0800 912 2999



Dig Sites

Area:

Line:



Low Pressure (LP) 21mbar – 75mbar



Medium Pressure (MP) 350mbar – 2bar



Intermediate Pressure (IP) 2bar – 7bar



High Pressure (HP) >7bar



Change of Diameter



End Cap



Depth of cover



Line/Fire Valve



Governor Station

EXTREME CAUTION.
Major Accident Hazard Pipeline in Vicinity
****RISK OF DEATH OR SERIOUS INJURY****
Prior to excavation starting you must contact the plant protection team on 02920 278912

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with H5(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Date Requested: 15/02/2019
Job Reference: 14851396
Site Location: 265772 191819
Requested by: Mr Sam Pogson
Your Scheme/Reference: asdf

Scale: 1:1250 (When plotted at A4)

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2019. All rights reserved. Ordnance Survey Licence number 0100044308.

Smell gas?
Call the Gas Emergency Service on
0800 111 999.


Dial
before
you dig

We need
10 days'
notice

Dial
Call **029 2027 8912**
before you start work.

Investigate
Before you dig, make sure
you know what's below.

Go ahead
Done your research?
Now you can dig safely.



Warning: PDF designed for A4 colour print only with no page scaling



Contact Us

Mapping Enquiries:

All areas 02920 278 912

General Enquiries:

All areas 0800 912 2999



Dig Sites

Area:

Line:



Low Pressure (LP) 21mbar – 75mbar



Medium Pressure (MP) 350mbar – 2bar



Intermediate Pressure (IP) 2bar – 7bar



High Pressure (HP) >7bar



Change of Diameter



End Cap



Depth of cover



Line/Fire Valve



Governor Station

EXTREME CAUTION.
Major Accident Hazard Pipeline in Vicinity
****RISK OF DEATH OR SERIOUS INJURY****
Prior to excavation starting you must contact the plant protection team on 02920 278912

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Date Requested: 15/02/2019
Job Reference: 14851396
Site Location: 265772 191819
Requested by: Mr Sam Pogson
Your Scheme/Reference: asdf

Scale: 1:1250 (When plotted at A4)

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2019. All rights reserved. Ordnance Survey Licence number 0100044308.

Dial
before
you dig


We need
10 days
notice

Smell gas?
Call the Gas Emergency Service on
0800 111 999.

Dial
Call 029 2027 8912
before you start work.

Investigate
Before you dig, make sure
you know what's below.

Go ahead
Done your research?
Now you can dig safely.



Contact Us

Mapping Enquiries:

All areas 02920 278 912

General Enquiries:

All areas 0800 912 2999



Dig Sites

Area:

Line:



Low Pressure (LP) 21mbar – 75mbar



Medium Pressure (MP) 350mbar – 2bar



Intermediate Pressure (IP) 2bar – 7bar



High Pressure (HP) >7bar



Change of Diameter



End Cap



Depth of cover



Line/Fire Valve



Governor Station

EXTREME CAUTION.
Major Accident Hazard Pipeline in Vicinity
****RISK OF DEATH OR SERIOUS INJURY****
Prior to excavation starting you must contact the plant protection team on 02920 278912

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2019. All rights reserved. Ordnance Survey Licence number 0100044308.

Date Requested: 15/02/2019
Job Reference: 14851396
Site Location: 265772 191819
Requested by: Mr Sam Pogson
Your Scheme/Reference: asdf

Scale: 1:1250 (When plotted at A4)

Dial
before
you dig


We need
10 days'
notice

Smell gas?
Call the Gas Emergency Service on
0800 111 999.

Dial
Call **029 2027 8912**
before you start work.


Investigate
Before you dig, make sure
you know what's below.


Go ahead
Done your research?
Now you can dig safely.



Warning: PDF designed for A4 colour print only with no page scaling

 Contact Us Mapping Enquiries: All areas 02920 278 912 General Enquiries: All areas 0800 912 2999	 <table border="0"> <tr> <td>Dig Sites</td> <td>Area: </td> <td>Line: </td> </tr> <tr> <td></td> <td colspan="2">Low Pressure (LP) 21mbar – 75mbar</td> </tr> <tr> <td></td> <td colspan="2">Medium Pressure (MP) 350mbar – 2bar</td> </tr> <tr> <td></td> <td colspan="2">Intermediate Pressure (IP) 2bar – 7bar</td> </tr> <tr> <td></td> <td colspan="2">High Pressure (HP) >7bar</td> </tr> </table> <table border="0"> <tr> <td></td> <td>Change of Diameter</td> <td></td> <td>Line/Fire Valve</td> </tr> <tr> <td></td> <td>End Cap</td> <td></td> <td>Governor Station</td> </tr> <tr> <td></td> <td>Depth of cover</td> <td></td> <td></td> </tr> </table>	Dig Sites	Area: 	Line: 		Low Pressure (LP) 21mbar – 75mbar			Medium Pressure (MP) 350mbar – 2bar			Intermediate Pressure (IP) 2bar – 7bar			High Pressure (HP) >7bar			Change of Diameter		Line/Fire Valve		End Cap		Governor Station		Depth of cover			EXTREME CAUTION. Major Accident Hazard Pipeline in Vicinity **RISK OF DEATH OR SERIOUS INJURY** Prior to excavation starting you must contact the plant protection team on 02920 278912
Dig Sites	Area: 	Line: 																											
	Low Pressure (LP) 21mbar – 75mbar																												
	Medium Pressure (MP) 350mbar – 2bar																												
	Intermediate Pressure (IP) 2bar – 7bar																												
	High Pressure (HP) >7bar																												
	Change of Diameter		Line/Fire Valve																										
	End Cap		Governor Station																										
	Depth of cover																												
Date Requested: 15/02/2019 Job Reference: 14851396 Site Location: 265772 191819 Requested by: Mr Sam Pogson Your Scheme/Reference: asdf Scale: 1:1250 (When plotted at A4)	IMPORTANT NOTICES - This information is given as a guide only and its accuracy cannot be guaranteed - The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter - Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated - You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used - It is your responsibility to ensure this information is provided to all persons working near our plant - If in doubt call the WWU dig team on 02920 27891 Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA 0800 111 999	Smell gas? Call the Gas Emergency Service on 0800 111 999. Dial before you dig Call 029 2027 8912 before you start work. Investigate Before you dig, make sure you know what's below. Go ahead Done your research? Now you can dig safely. We need 10 days' notice																											





Warning: PDF designed for A4 colour print only with no page scaling



Contact Us

Mapping Enquiries:

All areas 02920 278 912

General Enquiries:

All areas 0800 912 2999

100m

Dig Sites

Area:

Line:

Low Pressure (LP) 21mbar – 75mbar

Medium Pressure (MP) 350mbar – 2bar

Intermediate Pressure (IP) 2bar – 7bar

High Pressure (HP) >7bar

Change of Diameter

End Cap

Depth of cover

Line/Fire Valve

Governor Station

EXTREME CAUTION.
Major Accident Hazard Pipeline in Vicinity
****RISK OF DEATH OR SERIOUS INJURY****
Prior to excavation starting you must contact the plant protection team on 02920 278912

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Date Requested: 15/02/2019
Job Reference: 14851396
Site Location: 265772 191819
Requested by: Mr Sam Pogson
Your Scheme/Reference: asdf

Scale: 1:1250 (When plotted at A4)

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2019. All rights reserved. Ordnance Survey Licence number 0100044308.

Smell gas?
Call the Gas Emergency Service on
0800 111 999.

Dial
before
you dig

We need
10 days
notice

Dial
Call **029 2027 8912**
before you start work.

Investigate
Before you dig, make sure
you know what's below.


Go ahead
Done your research?
Now you can dig safely.

21


Warning: PDF designed for A4 colour print only with no page scaling



Contact Us
Mapping Enquiries:
 All areas 02920 278 912
General Enquiries:
 All areas 0800 912 2999



EXTREME CAUTION.
 Major Accident Hazard Pipeline in Vicinity
****RISK OF DEATH OR SERIOUS INJURY****
 Prior to excavation starting you must contact the plant protection team on 02920 278912



Date Requested: 15/02/2019
 Job Reference: 14851396
 Site Location: 265772 191819
 Requested by: Mr Sam Pogson
 Your Scheme/Reference: asdf

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Scale: 1:1250 (When plotted at A4)

Dial before you dig


Smell gas?
 Call the Gas Emergency Service on 0800 111 999.

Dial
 Call 029 2027 8912 before you start work.

Investigate
 Before you dig, make sure you know what's below.

Go ahead
 Done your research? Now you can dig safely.

We need 10 days' notice



Warning: PDF designed for A4 colour print only with no page scaling



Contact Us

Mapping Enquiries:

All areas 02920 278 912

General Enquiries:

All areas 0800 912 2999



Dig Sites

Area:

Line:



Low Pressure (LP) 21mbar – 75mbar



Medium Pressure (MP) 350mbar – 2bar



Intermediate Pressure (IP) 2bar – 7bar



High Pressure (HP) >7bar



Change of Diameter



End Cap



Depth of cover



Line/Fire Valve



Governor Station

EXTREME CAUTION.
Major Accident Hazard Pipeline in Vicinity
****RISK OF DEATH OR SERIOUS INJURY****
Prior to excavation starting you must contact the plant protection team on 02920 278912

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Date Requested: 15/02/2019
Job Reference: 14851396
Site Location: 265772 191819
Requested by: Mr Sam Pogson
Your Scheme/Reference: asdf

Scale: 1:1250 (When plotted at A4)

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2019. All rights reserved. Ordnance Survey Licence number 0100044308.

Smell gas?
Call the Gas Emergency Service on
0800 111 999.

Dial
before
you dig

We need
10 days'
notice

Dial
Call **029 2027 8912**
before you start work.

Investigate
Before you dig, make sure
you know what's below.


Go ahead
Done your research?
Now you can dig safely.

23

Warning: PDF designed for A4 colour print only with no page scaling



Contact Us
Mapping Enquiries:
 All areas 02920 278 912
General Enquiries:
 All areas 0800 912 2999



EXTREME CAUTION.
 Major Accident Hazard Pipeline in Vicinity
****RISK OF DEATH OR SERIOUS INJURY****
 Prior to excavation starting you must contact the plant protection team on 02920 278912

[Valve Symbol] Line/Fire Valve
 [Governor Symbol] Governor Station

Date Requested: 15/02/2019
 Job Reference: 14851396
 Site Location: 265772 191819
 Requested by: Mr Sam Pogson
 Your Scheme/Reference: asdf

IMPORTANT NOTICES

- This information is given as a guide only and its accuracy cannot be guaranteed
- The plan only shows those pipes owned by Wales & West Utilities (WWU) as its role as a licensed Gas Transporter
- Service pipes, valves, syphons, stub connections etc. may not be shown but their presence should be anticipated
- You must use safe digging practices in accordance with HS(G)47 to establish the actual position of mains, services and other apparatus before any mechanical excavation is used
- It is your responsibility to ensure this information is provided to all persons working near our plant
- If in doubt call the WWU dig team on 02920 27891

Report damage immediately – KEEP EVERYONE AWAY FROM THE AREA
0800 111 999

Scale: 1:1250 (When plotted at A4)

Crown Copyright © - Reproduced by permission of Ordnance Survey on behalf of HMSO. And database right 2019. All rights reserved. Ordnance Survey Licence number 0100044308.

Smell gas?
 Call the Gas Emergency Service on
0800 111 999.

Dial before you dig

We need 10 days' notice

Dial
 Call **029 2027 8912**
 before you start work.

Investigate
 Before you dig, make sure you know what's below.

Go ahead
 Done your research?
 Now you can dig safely.