


Putting in to Polar form



$$0.375 + 0.25j$$

$$r^2 = 0.25^2 + 0.375^2$$

$$r = \sqrt{0.25^2 + 0.375^2}$$

$$r = \sqrt{0.141 + 0.0625}$$

$$r = \sqrt{0.2035}$$

$$r = 0.451$$

$$\tan \theta = \frac{0.25}{0.375}$$

$$\theta = \tan^{-1} \left(\frac{0.25}{0.375} \right)$$

$$\theta = 33.69^\circ$$