


If component tested with higher
load must be reduced to see

Fatigue strength/cycles under zero



Gerber is the most optimistic of
the most stress sensitive