


Question 1

- © Non-linearity is the maximum error for either an input or output when an output curve is produced and is given as a percentage of its full range.



from diagram calculated
as $(x/X) \times 100$
to give as percentage
of full range.