

Cory Allen - 1503528
M6X00420
Advanced Stress Analysis + FEA

2AM 2.1 of 6

5/2/21

Q1) C) ~~Confidence can be increased~~

Confidence can also be increased by Strain gauging, undertaking Natural Frequency comparison, dynamic response comparison and temperature and Pressure distribution comparison.

Understanding that 10-15% difference in results is considered good Correlation