




Starting from point 0,0 draw a Polyline to depict walls to the dimensions shown.

To start type PL or select Polyline from the Ribbon.

type 0,0 and press enter

now use the coordinates system to enter the next point (s) of the polyline pressing enter after each until you Close the polyline

@500,0 (enter)

@0,300 (enter)

@-200,0 (enter)

and so on.

remember the @ symbol means you are moving in a direction.

the first distance value before the comma are along the 'x' axis

the second distance value after the comma are along the 'y' axis

adding a minus before an x distance will move the line from right to left direction

adding a minus before a y distance will move the line down the Y axis.