


compression is compressive. The weight is affected by a stress, the more weight is used, the less cyclic loading will occur. The less weight/stress then the number of cycles leading increases.

S/N

Experimental Test + Result

Its mean stress

increases. S/N curve moves downwards



S/N curve includes the acceptance of the exact specimen give vastly varying results. A number of samples are tested at the same stress and thus a more diverse