




						Notes The edges of surrounding buildings were not surveyed; buildings will obstruct the signal between the GPS receiver and the satellites above, this lowers the number of satellites that the receiver can communicate with, resulting in a higher PDOP and inaccurate results. The weather conditions at the time of survey was heavy rain and wind, which may have caused the antenna and pole to shake when taking readings.	Client ROBYN LEWIS Scale (A3) 1:200 Datum NEWLYN		Project SA1 CAMPUS Title SITE SURVEY		ALT Surveying Project Code Drawing No. Issue 1 1		
1	FIRST ISSUE	AA			04-23								
Issue	Description	Auth.	Ckd.	Appd.	Date								